

**Muncy Creek Township Parks, Recreation, & Open Spaces Advisory  
Board**

Meeting Minutes- MAr 15th, 2026 - 1:00 PM

The meeting was held at Kiess Park, called to order and roll call by Brian Vann at 1:05pm Sunday March 15th, 2026.

**Members Present:** Laurie Stryker, Rebekah Rosario, Tiffany Soloman, Eric Newcomer, Brian Vann

**Members Absent:** Brittany Reynolds, Frank Guardini

1. Members who were present walked through Kiess park to evaluate the equipment, ground, and buildings.
2. Board members formed a recommendation list to present to the MCT Board of Supervisors. The list is attached.

Meeting concluded at 2:25pm

Next Meeting: Monday April 13th, 6:00 pm at Township Building

**Muncy Creek Township**  
**Parks, Recreation, and Open Spaces Advisory Board**  
**Observations for Recommendations**

- Attachment to 3.15.2026 Board Minutes

**High Priority:**

1. Observed concession stand roof wear and tear. Recommend replacement of shingles and there appears to be possible sheeting damage underneath. We viewed buckling, rolling, dipping in roof lines and shingles along with water damage in wood. Please consider steel. The Gable end on the home plate side has a ton of weather damage and needs R&R.
  
2. Dug out roofs:
  - A) lighted field dugouts will need shingle replacement, some sheeting. Consider steel
  - B) President's field dugouts need sheeting, fascia, and shingles. Consider steel.
  - C) Junior's Field dugouts will need shingles replaced, Consider steel. Least amount of damage of the three fields. May consider scheduling in a later year along with several picnic table roofs.
  
3. Lumber curbing around the playground area is very aged, loose, broken. Replacement with new lumber recommended and consider possible options such as concrete.
  
4. There are several repairs needed at the Swing Kingdom Adventure set.
  - A) There is a broken step that needs to be replaced.
  - B) Two tube slides are boarded off and cannot be used. The very top tube segments need to be replaced. A 3rd slide has what appears to be some contact damage that may need filed off. Should be structurally sound.
  - C) All Rope elements should be replaced. A climbing web, two ropes at the climbing walls, and the ropes on the tire swing. A hand hold is missing on a wall.

D) There is a ramp with “weakened” treads that may need to be replaced. A few vinyl post caps are missing. Pressure washing would add to the enjoyment of this Playset. Overall we unanimously thought the playset is in good structural condition and merits full repair. The entire playground area is an outstanding asset for our community. Some raking and mulch additions should be considered.

5. There are several benches in which the lumber is in very poor condition and repair is recommended.

Moderate Priority:

1. Additional benches with shading inside/alongside the playground area and along the walking path.
2. Additional playset equipment for the playground such as an obstacle or confidence course.
3. Add sand, maybe relocate or remove tractor tires.
4. Paint the Pavillion floor and benches.
5. Fencing, sill plates, and bat holders on several dugouts could use R&R.
6. Extend the walking/running path to the lot on the opposite side of the tree line on western end of the park.
7. Resurface basketball court. Consider splitting into half basketball court half some other activity.
8. Is there space for a golf chipping or putting area?

END